





WIRING DIAGRAM




Fasten Fuse Boxes
So Wires Point Down




Power: red=on / green=off
Mode: red=spot / green=driving



Not Supplied By PIAA



+ Switch Power



+ Marker Lamp Power

